

Dun-Movin' Earthworks

Machinery Log

Machine: Caterpillar 980K Loader

Serial No. W7K02521 Reg No. 50272C

ID NO: DME044

DATE	Milage/Hours	A/B/C	REPAIRS CARRIED OUT
21/12/2018	1718.4		Arrived on site at Chillagoe. Inspected by Auctus.
22/12/2018			Loader has slow cycle time. Contacted Hastings field service to advise. Hastings Field Service to be on site 23/12/18.
23/12/2018			Hastings Field Service on site to diagnose fault. Diagnosed Hydraulic pump as faulty. Sourcing new pump. Machine is slower then others but Ok to use if required,
24/12/2018			Fit digital radio
4/01/2019	1742		Machine floated back to Cairns to have Hydraulic pump replaced
10/01/2019			Machine back on site
18/01/2019	1889		New cutting edges fitted.
22/01/2019			Replace grease lines on boom
24/01/2019			Loosen cutting edge bolts to clean dirt out. Retighten bolts and use bar.
28/02/2019	2588		Repaired leaking hydraulic line at crowd cylinder. Repaired step, and filled auto greaser. Turned cutting edges
11/03/2019	2807		Engine valve set performed by Hastings Deering.
11/03/2019	2807		500 Hr Service.
19/03/2019	2907		Replace cutting edges with 50mm edge set. Inspect RH crowd hose for leakage. Weeping at crimp. Not replaced
19/03/2019			Rotate front wheels to rear and rear to front.
20/03/2019			Recheck all wheel nuts for tightness. Recheck cutting edge bolts
24/03/2019			Replace door strut
5/04/2019			Has exhaust leak at band clamp at muffler. Monitor
6/04/2019			Fit LHS lower tilt cylinder hose.
9/04/2019	3260		Service. Engine oil and filter replaced. Transmission filter changed and transmission oil drained and filled with new TDTO30 oil. All fuel filters replaced and hydraulic filters replaced. Oil samples taken of the engine, trans, hydraulic system and both diffs.
11/04/2019			Replace inner and outer air filter. Fill auto greaser
27-Apr			Grease machine and blow out Outer Air filter
13/05/2019	3600		Service. New engine and fuel filters. Outer air filter replaced.
17/05/2019			Fill auto greaser
28/5			Replace Pos 2 with second hand tyre due to rock cut in sidewall
31/05/2019			Fill auto greaser
2/06/2019			Replace Pos 1 tyre with second hand tyre due to rock cut in sidewall
4/06/2019			Fill auto greaser, blow out outer air filter.
7/06/2019			Pos 1 Tyre cut. Awaiting new tyres.
13/06/2019	3925		4 x New Tyres Fitted.
14/06/2019	3925		Service. Oil filter and fuel filters replaced. 38 Ltrs Cat oil.
19/07/2019	4227.6		Park Brake Solenoid replaced

25/07/2019			4227.6 Hours : Hydraulic pump 2485.6 hrs : Tyres 302.6 hrs
			All receipts available for CAT servicing and fitting of Hydraulic pump